

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul FITZGERALD BPB No.0119	360	40 Kingsland Road, Bexley 42 Kingsland Road, Bexley	Mr Fitzgerald issued a construction certificate when the plans forming part of the construction certificate were inconsistent with the development consent. Mr Fitzgerald failed to ensure that building works proceeded in accordance with construction certificate and development consent. Mr Fitzgerald issued a construction certificate and nominated an incorrect classification under the Building Code of Australia. This had significant adverse impact on the requirements for fire separation and protection of openings in the building. Mr Fitzgerald issued complying development certificates for two buildings that contained a basement each and required excavations to a depth greater than 1.0 m, contrary to the requirements of Exempt and Complying Development Codes (SEPP) 2008.	 Mr Fitzgerald is: Reprimanded; Fined \$25,000; Mr Fitzgerald's certificate of accreditation is cancelled; Mr Fitzgerald cannot reapply for accreditation for a period of (5) five years from 8 May 2013. The decision on penalty is an aggregation of determinations of three complaints investigations in relation to four developments as specified. 	15 March 2013 (Building Professionals Board) and 8 May 2014 (NSW Civil & Administrative Tribunal)



Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
	565 Military Road, Mosman	Mr Fitzgerald issued a complying development certificate on the basis of a deficient application. The application did not contain specifications or plans describing or depicting the building work. Mr Fitzgerald issued a final occupation certificate when the building was not suitable for occupation or use in accordance with its classification under the Building Code of Australia: Mr Fitzgerald failed to ensure the integrity of the fire protective ceiling covering separating the two levels of the subject building was addressed. Mr Fitzgerald failed to ensure the structural adequacy of the building was appropriately addressed.		