

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Terry WEST	164	2 Lock Street BLACKTOWN	During the last critical stage inspection, the certifier failed to detect that the enclosure/cupboard constructed under the fire isolated stairs meet the	Mr West was reprimanded and fined \$2000	23 Apr 2008
BPB No. 0438			deem-to-satisfy provisions contained in the Building Code of Australia The fire safety certificate issued with the occupation certificate did not include all nominated fire safety measures Over an extended period of time, the certifier failed to correct discrepancies between the fire safety schedule and the fire safety certificate	πιου ψ2000	