

## **Summary of Disciplinary Action**

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Robert <b>WOOD</b>	361	Unit 2, 22-38 Fitzroy Street, Marrickville	<ol> <li>Carried out an inspection of a development site prior to the issue of a construction certificate without there being a</li> </ol>	Mr Wood was cautioned	20 May 2013
BPB No. 1736			development consent in force and prior to the receipt of the application for the construction certificate.		
			<ol> <li>Failure to record details of an inspection as required by clause 143C (3) (i) and (j) of the Environmental Planning and Assessment Regulation 2000.</li> </ol>		