

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
David SEAL	368	658 Lyne Street, Lavington	 Failure to identify during inspections, the setback of the building from the western boundary was not constructed as per the development consent. 	Mr Seal was cautioned	18 December 2013
BPB No.0368			 Failure to identify during inspections, two articulation joints to brickwork on the eastern wall were not installed as required by the structural drawings. 		
			 Failure to ensure that mass concrete blinding under the stiffened raft slab as detailed in structural drawings was constructed. 		