

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Bryan COLLUM BPB No. 0069	326	21 Noble Street, Mosman	Mr Collum accepted appointment as the principal certifying authority by the builder instead of the owner and did not keep a record of inspection as required by the Environmental Planning and Assessment Regulation.	Mr Collum's conduct was unsatisfactory professional conduct but no further action is taken.	27 October 2011