

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Richard MOY BPB No. 0281	172	6 Killarney Street MOSMAN	<p>The certifier failed to issue a notice on the developer after it was apparent that the work being carried out on site, which caused the raising of the ground level by 500mm, was not complying with the development consent</p> <p>The certifier failed to issue a notice, prior to issuing the occupation certificate, requiring the removal of the unauthorised landfill in order for the development to comply with the development consent</p> <p>The certifier issued a final occupation certificate prior to ensuring all conditions of the development consent had been complied with namely that the external ground levels are consistent with the development consent</p>	Mr Moy was cautioned	10 Jun 2008