

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Terry <b>WEST</b>  BPB No. 0438	176	12 John Street HUNTERS HILL	The certifier issued a construction certificate that was inconsistent with the plans approved by the development consent, namely the en-suite window to the northern end of the eastern wall had been re-positioned	Mr West was cautioned	27 Jun 2008