

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Jon HALL BPB No. 0157	183	5 Glendon Road DOUBLE BAY	The certifier failed to comply with the code of conduct requirements failing to act in a proper manner towards a member of the public	Mr Hall was cautioned	31 Jul 2008