

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Gurdeep SINGH BPB No. 0377	234	74B Anthony Road DENISTONE	The certifier failed to obtain the consent of one of the owners of the land to the making of the application for the construction certificate	Mr Singh was cautioned	2 Jul 2009