

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Antonius GINDI BPB no. 0137	254	35 Breakfast Road, Marayong	Mr Gindi issued a construction certificate which did not comply with pre-conditions of consent. The construction certificate also included subdivision works. Mr Gindi is not accredited to issue construction certificates for subdivision works.	Mr Gindi was reprimanded, fined the sum of \$1000 and required to successfully complete a specified education course.	29 October 2009