



Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ronald MOORE BPB No. 0274	336	136, 154 and 156 Island Point Road, St Georges Basin	Mr Moore issued a construction certificate for the clearing of land. This is not considered to be building or subdivision work and therefore a construction certificate should not have been issued.	Mr Moore was reprimanded.	5 April 2012