

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ken SMITH	356	33 Wason Street, Ulladulla	Mr Smith issued an interim occupation certificate for a building that was not suitable for occupation or use in accordance with its classification under the	Mr Smith was reprimanded and ordered to a pay a	13 Dec 2012
BPB No. 0789			Building Code of Australia as access for people with disabilities had not been provided to the new entry to the development.	fine of \$1000.	