

Summary of Disciplinary Action

Accredited certifier	Disciplinary Action No.	Complaint No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Andrew DUGGAN BPB No. 0101	421	78/13	88 Vintage Lakes Drive, Tweed Heads South	<p>Mr Duggan failed in his role as a principal certifying authority to ensure that a building complied with the BCA deemed-to-satisfy provisions regarding sub-floor ventilation.</p> <p>Mr Duggan performed the role of a principal certifying authority whilst not accredited between 26 September 2011 and 17 November 2011.</p>	Mr Duggan was reprimanded and required to undertake the UTS 'Certification Short Course' within 12 months.	9 Feb 2016