

## **Summary of Disciplinary Action**

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Lyall	311	30-34 Hilly	Mr Dix failed to provide adequate timely	Reprimand	23 June
DIX		Street, Mortlake	response in relation to correspondence about alleged non compliance of the development		2011
BPB No. 0092			consent.		
0092			Mr Dix issued a Notice of Commencement of		
			Building Work and Appointment of Principal		
			Certifying Authority which contained incorrect information about his accreditation number and		
			the accreditation body.		