

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
First Troy MYERS BPB No. 284	357	18 Primula Street, Lindfield	The accredited certifier issued a complying development certificate that did not comply with development standards in relation to side and rear boundary setbacks	Mr Myers was Reprimanded	26 February 2013