

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Donald <b>FERGUSON</b>  BPB No. 0117	364	10 Morwong St, Tuross Head	Whilst undertaking a critical stage inspection, Mr Ferguson failed to detect that the framework for a deck did not comply with the structural engineering drawings.	Mr Ferguson was cautioned and fined the sum of \$2000	11 July 2013