

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ronald MOORE BPB 0274	444	3 Corella Close, Berkley Vale	 Issued a construction certificate (CC) for a warehouse building (BCA classes 5 & 8) with plans and specifications that did not demonstrate compliance with the relevant BCA requirements (Part C2). Issued the abovementioned CC after the building works to which the CC relates had already commenced. 	Mr Moore was Reprimanded and an additional condition was placed on his certificate of accreditation (for the 24 month period between 21 August 2017 to 21 August 2019) stating: Prior to issuing a complying development certificate (CDC) or a construction certificate (CC) Mr Moore must obtain a peer review report from another accredited certifier, who holds a relevant certificate of accreditation, that confirms in writing that the proposed work complies with the relevant deemed-to-satisfy requirements of Sections C, D and E of the Building Code of Australia. The condition does not apply to the following: a) class 1a and class 10 buildings; b) class 2 to 9 buildings with a maximum rise in storeys of three storeys and a maximum floor area of 2,000m²; c) buildings with a maximum rise in storeys of four storeys in the case of a building that comprises only a single storey of class 7a carpark located at the ground floor level or basement level and with three storeys of class 2 above, and with a maximum floor area of 2000m²; d) fitout works within an existing retail or commercial tenancy in a class 5 or 6 part of a building. For the purposes of the above 'a relevant certificate of accreditation' is a current certificate of individual accreditation that authorises the holder to issue CDCs, CCs, compliance certificates and occupation certificates, and to act as the principal certifying authority, in regard to class 2 to 9 buildings that exceed the limitations of b), c) and d) above.	17 August 2017