

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ross NEWPORT BPB No. 0293	161	26 River Road ELDERSLIE	The certifier failed to safeguard the interests of the public, failed to act objectively and/or impartially, act honestly and failed to bring due care and diligence upon the discharge of their duties in denying any involvement with a development when they were appointed as the principal certifying authority	Mr Newport was cautioned	23 Apr 2008