

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul <b>PEARCE</b>  BPB No. 0322	236	1 Botanic Road MOSMAN	The certifier failed to identify the classification of the building to which the construction certificate relates	Mr Pearce was found guilty of unsatisfactory professional conduct but no further action was taken	13 Aug 2009