

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Lyall DIX BPB No. 0092	246	36 Ellam Drive SEVEN HILLS	The certifier, prior to issuing the occupation certificate, failed to ensure conditions of consent had been satisfied that were pre-conditions to the issuing of the occupation certificate including conditions relating to certification of on-site stormwater, land survey, construction inspections, certification of building insulation, common area embellishment, retaining wall construction and works-as-executed plans and certification	Mr Dix was cautioned	17 Sept 2009