

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Glenn FITZGIBBON BPB No. 0120	256		Mr Fitzgibbon failed to detect defective work during a critical stage inspection and allowed the construction of an alteration to a house to progress.	Mr Fitzgibbon was cautioned.	29 October 2009.