

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Trenton <b>McCURLEY</b> BPB No. 0256	162	8 Bridgewater Boulevard CAMDEN PARK	While undertaking a frame inspection for a dwelling, the certifier failed to disclose framing defects, namely trust fixing and tie down requirements	Mr McCurley was reprimanded	23 Apr 2008