

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Mark COGO BPB No. 0066	247	2 Bay Drive MEADOWBANK (formerly 145 – 147 Bowden Street, Meadowbank)	<p>The certifier issued a construction certificate that was inconsistent with the plans approved by the development consent namely altering the layout of the restaurant resulting in:</p> <ul style="list-style-type: none"> ▪ a cool room being located within a car parking space, ▪ a new doorway been created within the northern wall of the restaurant, and ▪ a new car parking layout being provided to accommodate the cool room 	Mr Cogo was cautioned	17 Sept 2009