

Summary of Disciplinary Action

Accredited certifier	Disciplinary Action No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Dean GOLDSMITH BPB No.0141	322	373-375 The Entrance Road, Erina Heights	Mr Goldsmith issued a construction certificate that was inconsistent with the development consent. Specifically, the construction certificate plans approved a retaining wall in the area where the drawings approved by the development consent showed soft landscaping.	Mr Goldsmith is cautioned.	22 September 2011