

## Summary of Disciplinary Action

Accredited certifier	Disciplinary Action No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Michael <b>GOOLEY</b> BPB No. 0143	376	289 Elizabeth Mitchell Drive, Thurgoona	<ul style="list-style-type: none"> <li>Mr Gooley as the principal certifying authority for the development failed to ensure that the required smoke proof walls were installed in accordance with specification C2.5 (Smoke proof walls in aged care buildings) of the Building code of Australia.</li> <li>Mr Gooley as the principal certifying authority for the development issued occupation certificates for the development when the building was not suitable for occupation in accordance with its classification under the Building Code of Australia.</li> </ul>	Mr Gooley was reprimanded and fined the sum of \$5,000.	21 October 2014