

Summary of Disciplinary Action

Accredited certifier	Disciplinary Action No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
William Nettleton BPB No.0292	386	2/77 Harriett St, Waratah	Mr Nettleton issued a final occupation certificate for a dwelling when there was no sub-floor ventilation provided to a suspended timber-framed ground floor.	Mr Nettleton was reprimanded and fined the sum of \$3,500.	30 April 2015