

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Complaint No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Gurdeep <b>SINGH</b>  BPB No. 0377	415	79/14	12-14 Rupert Street Merrylands	Issued a CDC for developments (dwellings) that are not complying development under the Codes SEPP.	The Board finds that the conduct of Mr Gurdeep Singh constitutes unsatisfactory professional conduct as defined by section 19 of the Building Professionals Act 2005. Mr Singh is:  1. Reprimanded, and  2. Fined \$5,000.	26 Nov 2015