



**Fair  
Trading**

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary decision	Date of decision
Glenn <b>LEVICK</b>  BPB No. 0227	475	14/264-270 Lawrence Hargrave Drive, Thirroul.	Mr Levick issued an interim occupation certificate (OC) for an addition of five residential units which he could not reasonably have determined were suitable for occupation and would not constitute a hazard to the occupants. He also accepted an inadequate fire safety certificate and failed to forward to the council within two days a copy of the OC and its related documents.	Mr Levick was reprimanded and ordered to complete the UTS Advanced Building Regulation course.	11 December 2018