

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Barry JOHNSON BPB No. 0199	153	580 Botany Road ALEXANDRIA	The certifier issued an interim occupation certificate in respect of a commercial and residential development in the absence of the building relating to a number of matters relating to fire safety	Mr Johnson was cautioned	25 Feb 2008