

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ronald MOORE BPB No. 0274	194	264-270 Lawrence Hargrave Drive and 1-3 Redman Avenue THIRROUL	The certifier approved plans, as part of the construction certificate, that are inconsistent with the description of the works as contained on the determination The construction certificate issued by the certifier had no effect as it was issued after the building work to which it relates had already physically commenced on the site	Mr Moore was reprimanded and fined \$1000	5 Nov 2008