

Summary of Disciplinary Action

| Accredited certifier | Disciplinary action no. | Property address | Details of disciplinary matter | Disciplinary action | Date of decision |
|---|-------------------------|--|--|--|------------------|
| Richard MOY BPB No. 0281 | 215 | 29 Kildare Road BLACKTOWN and 72-78 Constitution Road MEADOWBANK | The certifier issued a Fire Safety Schedule (attached to the construction certificate) which omitted fire containment measures The certifier issued an occupation certificate in circumstances where the roof framing type was not in accordance with the plans approved by the construction certificate and were there was a defect in the frame constructed | Mr Moy was reprimanded and fined \$7,500 | 19 Dec 2009 |