

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Anthony <b>KANE</b> BPB No. 0205	263	38 Alkrington Avenue, Fishing Point	The certifier undertook and approved a frame inspection which later proved to be defective.	Mr Kane was reprimanded and fined \$500	3 December 2009