

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Glen <b>LEVICK</b> BPB 0227	273	467 Pacific Highway, Belmont.	Mr Levick: <ul style="list-style-type: none"> <li>issued a construction certificate that was inconsistent with the development consent.</li> <li>issued an occupation certificate when the building was not suitable for occupation.</li> <li>allowed an unauthorised door to be constructed to unit 2.</li> </ul>	Mr Levick was reprimanded	22 April 2010