

## **Summary of Disciplinary Action**

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Certifiei	action no.				decision
Peter	377	1065 Pittwater	Mr Dewick failed to provide the person with the	Mr Peter Dewick was	31 October
Dewick		Road Collaroy	benefit of the development consent with a list of the	cautioned.	2014
		,	mandatory critical stage inspections.		
BPB No. 090			, , , , , ,		