



**Fair  
Trading**

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary decision	Date of decision
Troy <b>MYERS</b>  BPB No. 0284	458	53 Karilla Avenue, Lane Cove North	Failed to take appropriate action as the principal certifying authority in regard to inadequate support for an external stair/landing prior to issuing a final occupation certificate.	Mr Myers was reprimanded and fined the sum of \$7,500.	30 August 2018