

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Bernard <b>COHEN</b>  BPB No. 0067	132	110A Hartington Street ROOTY HILL	The certifier issued a construction certificate that did not comply with the relevant requirements of the Building Code of Australia The certifier issued a final occupation certificate that was not in accordance with the original construction certificate The certifier failed to respond to correspondence prepared by council in a timely and efficient manner	Mr Cohen was reprimanded and fined \$1000	8 Jun 2007