

## Summary of Disciplinary Action

Accredited certifier	Disciplinary Action No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Peter <b>BOYCE</b> BPB No.043	285	18 Buckingham Street, Surry Hills	<p>Mr Boyce issued a final occupation certificate prior to compliance with a condition of development consent relating to the reconstruction of a portion of the common wall and installation of flashing to walls adjacent to the common boundary.</p> <p>Mr Boyce acted in the role of principal certifying authority without being formally appointed.</p> <p>Mr Boyce relied upon a structural engineer's certification that did not include the boundary/party walls.</p>	Mr Boyce was cautioned.	3 June 2010