

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Ramanathan SHANMUGANANTHAN BPB No. 0371	315	30-34 Hilly Street, Mortlake.	Mr Shanmugananthan issued a construction certificate without ensuring a condition precedent to the issue of the construction certificate in relation to amended plans which detailed specific sill heights, privacy screens and a retaining wall was satisfied.	Mr Shanmugananthan was reprimanded.	28 July 2011