

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Antonious GINDI BPB No 0137	438	55 Highfield Road, Lindfield	Mr Gindi failed to take action when the construction of the building was inconsistent with the development consent.	Mr Gindi is cautioned.	28 May 2014