

Board's Disciplinary Register

Accredited certifier	Disciplinary Action No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
George Watts BPB No. 0434	286	102-110 Parramatta Road, Homebush	Mr Watts issued a final occupation certificate for the building when tactile indicators were not installed, there were unsealed penetrations in slabs, a disabled car parking space was less than the minimum required width and the disabled toilet facility did not comply with the standard.	Mr Watts was cautioned.	3 June 2010