

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul GEARIN BPB No. 0132	265	167 Georges River Crescent, Oyster Bay	<ul style="list-style-type: none">Endorsed structural engineering drawings were inconsistent with development consent and construction certificate as they indicated construction work outside the development consent.	Mr Gearin was cautioned.	18 February 2010