

## Summary of Disciplinary Action

| Accredited certifier                   | Disciplinary action no. | Property address                | Details of disciplinary matter   | Disciplinary action          | Date of decision |
|--|-------------------------|---------------------------------|--|------------------------------|------------------|
| Gary<br><b>CHALMERS</b><br>BPB No.0059 | 276                     | 27 Wangara Street,<br>Doonside. | Mr Chalmers failed to identify during a critical stage inspection of the slab steel that the location of the proposed slab was not in the approved location. | Mr Chalmers was reprimanded. | 22 April 2010.   |