

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Michael LUDLOW BPB No. 0326	287	70 Ryde Road, Pymble	The certifier failed to ensure compliance with two conditions of the development consent in relation to the construction of a detached dual occupancy development.	Mr Ludlow was cautioned	15 July 2010