Summary of Disciplinary Action

Registered Certifier	Registration Number	Disciplinary Ground and Summary		Disciplinary Action	Date of Decision
Orlando Da Silva	BDC0081	 Engaged in unsatisfactory professional conduct under the <i>Building Professionals Act 2005</i> (NSW) by: a. Breaching section 109H(5)(c) of the EPA Act; and b. Engaged in conduct that falls short of the standard of competence, diligence and integrity that a member of the public is entitled to expect of a reasonably competent accredited certifier. Between 22 December 2015 and 29 September 2017 in relation to a development at 2-4 Aberdour Avenue, Rouse Hill NSW 2155, the Registered Certifier: Certified BCA compliance and issued an occupation certificate for the building, while the following readily observable non-compliances with the BCA were present in relation to the building:	 2. 3. 	to section 48(1)(b) of the BDC Act with immediate effect; Suspend the registration of the Registered Certifier in accordance with Part 2 for a period of two (2) years, pursuant to section 48(1)(e) of the BDC Act, with effect from 4:00pm on 31 August 2023; and	30/08/2023