

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Robert JONES BPB No. 0202	154	34-36 Barraran Street GYMEA BAY	<p>The certifier, appointed as the principal certifying authority, allowed construction works to be undertaken which were inconsistent with the construction certificate and the development consent namely planter pots were installed to the landscapes terraces of villas 2, 3 , 4 and 5 instead of the construction of planter boxes</p> <p>The certifier issued a final occupation certificate identifying a company name as the principal certifying authority as opposed to the individual who was appointed as the principal certifying authority.</p> <p>The certifier issued a final occupation certificate without firstly ensuring that all conditions of the development consent had been satisfied specifically Condition 63 which required a completion report to accompany the certificate</p>	Mr Jones was reprimanded and fined \$1000	4 Mar 2008