

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Kenyon	224	Various	The certifier issued a complying development certificate for a	Mr Hopkins was	21 May
HOPKINS		properties	dwelling and garage on rural zoned land, contrary to the	reprimanded	2009
			requirements (for a complying development) as contained in the		
BPB No. 0185			council's development control plan.		
			The certifier issued an interim and final occupation certificate		
			allowing for the floor and driveway levels to differ from those as		
			approved by the development consent		
			On two occasions the certifier issued a construction certificate failing		
			to identify their accreditation number on the certificate and the		
			classification of the building to which the certificate relates		
			The certifier issued both an interim and a final occupation certificate		
			that didn't contain the certifier's accreditation number		
			The certifier issued a complying development certificate for internal		
			alterations to a residential flat building, contrary to the requirements		
			contained within council's development control plan that does not		
			allow complying development certificates to be issued for internal		
			alterations to residential flat buildings		
			The certifier, as the principal certifying authority, issued an		
			occupation certificate failing to ensure that the development was		
			constructed in accordance with the development consent		
			The certifier, as the principal certifying authority, failed to ensure that		
			the development was carried out in accordance with conditions of		
			the development consent		
			The certifier issued a construction certificate for a development		
			without firstly ensuring that all pre-conditions of the development		
			consent had been complied with		