

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Lyll Dix BPB No. 0092	309	373-375 The Entrance Road, Erina Heights	Mr Dix issued a construction certificate that was inconsistent with the development consent. Mr Dix issued an interim occupation certificate prior to conditions of development consent being satisfied. Mr Dix failed to keep records of inspections in accordance with clause 162B of the Environmental Planning and Assessment Regulation.	Mr Dix was reprimanded and fined \$5000	2 May 2011