

## Board's Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul <b>ARAMINI</b>  BPB No. 0013	233	54 Kings Road VAUCLUSE	The certifier issued a construction certificate that was inconsistent with the development consent The certifier, having become aware that the development was not being constructed in accordance with the development consent, failed to take appropriate action	Mr Aramini was reprimanded and fined a sum of \$500	2 Jul 2009