

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Michael SHANAHAN BPB0370	288	18/621 Werombi Road Orangeville	<p>Mr Shanahan issued a construction certificate that did not comply with the requirements of the Building Code of Australia.</p> <p>Mr Shanahan issued a construction certificate in the absence of detailed building specifications.</p> <p>Mr Shanahan provided a copy of the construction certificate to Council that was accompanied by plans that were in part illegible.</p> <p>Mr Shanahan provided a copy of the BASIX certificate to Council that was not numbered or dated.</p>	Mr Shanahan was cautioned	15 July 2010