

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Fitzgerald Building Certifiers Pty Ltd Accreditation No. ABC 2	317	500-502 Willoughby Road Willoughby	The accredited body corporate issued a fire safety schedule with an incorrect classification. The schedule was corrected and a copy forwarded to the Board. A further copy that was to be relied upon and provided to Council as public record, included different fire safety measures. The accredited body corporate issued three different fire safety schedules for the same development.	Fitzgerald Building Certifiers Pty Ltd was reprimanded, fined \$2,000.00 and ordered to report on practice.	25 August 2011